## OHIO EPA COMMENTS CONCERNING COORDINATION AND COOPERATION BETWEEN PRRS AND FMPC

06/17/91

OEPA/DOE-FMPC/PADDYS
2
LETTER
OU5

ChieEPA
State of Ohio Environmental Protection Agency

Original File Copy

P.O. Box 1049, 1800 WaterMark Dr. Columbus, Ohio 43266-0149 (614) 644-3020 FAX (614) 644-2329

George V. Voinovich Governor

June 17, 1991

Mr. Gerald Westerbeck Site Manager U.S. DOE-FMPC P.O. Box 398705 Cincinnati, Ohio 45239

Mr. Grove Higgins
Project Manager
Paddys Run Road Site
P.O. Box 26683
Richmond, Virginia 23261-6683

## Gentlemen:

As we move forward with the remedial investigations of the Feed Materials Production Center (FMPC) and the Paddys Run Road Site (PRRS), it has become clear that contamination from both sites is significant and that close coordination and cooperation will be needed to characterize the type and extent of environmental releases. This will also be important in our efforts to perform removal actions to clean up contamination before final remedial decisions are made.

To this end, I am asking both sites and their contractors to improve communication and coordination efforts. These efforts should include frequent coordination meetings and the sharing of unvalidated lab data as soon as it is available. There is some risk associated with this but it seems worthwhile to speed up the

JUN 2 0 1991

Lead of the second seco

Printed on recycled paper

Mr. Gerald Westerbeck Mr. Grove Higgins June 17, 1991 Page 2

RI/FS process at both sites and possibly avoid mixing or influencing groundwater contaminant plumes. Ohio EPA will continue to assist in this coordination process. If you have any questions please contact Graham Mitchell in the Southwest District Office (513-285-6018).

Donne K. Schregarder

Donald R. Schregardus

Director

CC: Jenny Tiell, Ohio EPA
Donna Bohannon, OEPA-SWDO
Graham Mitchell, OEPA-SWDO
Catherine McCord, U.S. EPA
Pat Whitfield, U.S. DOE
Bill Britton, WMCO
John Wood, ASI
Tim Sainey, ERM
Steve Foard, Ruetgers-Nease
Bill Tims, A & W
John Razor, IT